A.V.W. EQUIPMENT


WRAP AROUND KAADY CONTOUR COMBO


Model -WACB2




The AVW WRAP AROUND operate on gravity.


No complicated controls because of the design it can self adjust to most Conveyor speed requirements. Simple design and low maintenance The AVW-Kaady Attached Contour Brush is constructed of heavy grade Stainless Steel. Designed to thoroughly clean the sides of vehicles through the use contouring adjustment. Van High brush height is ideal for vans and sport utility vehicles because it cleans the sides with smooth even pressure.


















A.V.W. Equipment Co. Inc. 105 South 9th Avenue, Maywood, IL, 60153 Phone: 708-343-7738 Fax: 708-343-9065 email: info@avwequipment.com Website: www.avwequipment.com





A.V.W. Equipment Co. Inc. 105 South 9th Avenue, Maywood, IL, 60153 Phone: 708-343-7738 Fax: 708-343-9065 email: info@avwequipment.com Website: www.avwequipment.com





		DRIVER		PASSENGER	
ITEM	Description	PART No.	QTY.	PART No.	QTY.
1	FASTENING BAR	WA1CB1AA			1
2	LEGS	WC3A			3
3	Z-CROSSBAR	WA1C-1566			1
-	Square Head Screw ½ "-13x1½"lg. (for sleeves) Hex Head Cap Screw 3/8"-16x2"lg. (fully threaded, for pillow block adj.	SQHS1213150 HHCS3816200F			8 8
4	PILLOW BLOCK 2" Screw Fastener Set ½" (for pillow block):	WA1WB			4 8
-	Hex Head Cap Screw ½"-13x2¼"lg.	HHCS1213225			8
-	Flat Washer ½"I.D.x1¼"O.D. Split Lock Washer ½"	FW12125 SLW1/2			16 8
-	Hex Nut ½"-13	HN1213			8
5/6	ARM ASSEMBLY:	WA1D	1	WA1E	1
5.1/6.1 5.2	Driver Arm 48 "lg./Pass. Arm 76" LG Rubber Stop Arm Assembly:	WA1DA WA1DB	1 2	WA1EA WA1DB	1 2
-	Stop Arm	WA1DBA	2	WA1DBA	
-	Rubber Bumper Screw Fastener Set 3/8" (for bumper):	WA1DBB -	2 2	WA1DBB -	$\begin{bmatrix} 2\\2 \end{bmatrix}$
-	Hex Head Cap Screw 3/8"-16x1 ¹ / ₄ "lg.	HHCS3816125	2	HHCS3816125	2 2 2 2 2 2 2
-	Flat Washer 3/8"I.D.x7/8"O.D. Hex Nut 3/8"-16	FW38087 HN3816	2 2	FW38087 HN3816	2 2
5.3	Adjustable Lower Rubber Stop ARM (OPTIONAL)	WA3DB-2639	1	WA3DB-2639	1
5.4	Square head screw 3/8"-16x 3/4 "lg. (for stop adj.) PLASTIC SPACER	SQHS3816075 WA11	4 2	SQHS3816075 WA11	4 2
5.5	2-PIECE COLLAR 1½"	WA2J-2P	2	WA2J-2P	2
7	SHOCK ABSORBER ASSEMBLY:	WA1FA			2
7.1 7.2	Shock Absorber UHMW bushing 3/8"I.D.	WA1FAA WA1FA1		2 4	
7.3	PIN Æ3/8"x6"lg.	WA1FB			4
7.4	COLLAR 3/8"	WAIFC			4
8 8.1	RETRACT KIT: AIR CYLINDER 2" x 10"	WA1GA AC2x10			2 2
8.2	Ball Joint Rod End	BJI-2-20		2	
8.3	Rear Mount -Clevis	WA2GA WA2GA1			2 2
-	-Threaded Rod 1/2"-13x5" LG	WA2GA2		2	
8.4	-Hex Nut 1/2"-13 Rear Pin 3/8" x 1/2" LG	HN213 WA1GB		6 2	
-	Cotter Pin	CP3-8		2 2	
8.5 8.6	Front Pin 1/2" x 2" LG Collar 1/2"	WA1GC WA1GD		2 2	
-	Jam Nut 1/2"	JN1220			2
9 7	WRAP STABILIZER ASSEMBLY Shock Absorber Assembly	WA2F-0318 WA2FA		2 2	
9.1	Rear Stabilizer Mount	WA2FC		2	
9.2 9.3	Stabilizer Bracket Kit Front Stabilizer Mount	WA2DAE WA2FB-0416		2 2	
9.3	TIOH Staumzer Mount	VV P	121 D-04	10	



ITEM	Description	DRIVER SIDE		PASSENGER SIDE	
		PART NO.	Qty	PART NO.	Qty
10/10A	ARM MOUNT ASSEMBLY UPPER/LOWER	CB2AB-U/CB2AB-L	1	CB2BB-U-CB2BB-L	1
10.1	Square U-Bolt Fastener set 1/2"	RB2ABB	4	RB2ABB	2
-	Square U-Bolt 1/2"x17"lg	UB-SQ050x1700	4	UB-050x1700	2
-	Split lock washer 1/2"	SLW1/2	8	SLW1/2	4
10.2	Hex Nut 1/2''-13 BUSHING for Upper Arm	HN1213 CB1ADCC	8 2	HN1213 CB1ADCC	4 2
10.2	BUSHING for Copper Arm	CB1ADCC CB1ADCD	2	CB1ADCD	2
10.3	ARM MOUNT PLATE UPPER/LOWER	CB1ABA-U/CB1ABA-L	1	CB1BBA-U/CB1BBA-L	1
11	BUMPER ASSEMBLY	(CB1AC	1	2
	2-Piece BUMPER MOUNT (w/Plate welded)	CB1ACA			2 2
-	Hex Head cap screw 3/8"-16x1-1/2"lg		HHCS3816150		
-	Split Lock Washer 3/8"		LW 3/		2
11.0	Hex Nut 3/8"-16		IN381		2 2 2 2 2
11.2	RUBBER STOP (BUMPER) Screw fastener set 3/8" (for bumper):	W	'A1DB	В	2
-	Hex head cap screw 3/8"-16x1½"lg.	нна	- CS3816	5125	2
_	Flat washer 3/8"x7/8"O.D.		W3808		$\frac{2}{2}$
-	Hex nut 3/8"-16		IN381		2
12	ARM ASSEMBLY	CB2AD	1	CB2BD	1
	(Arms w/Removable sleeves)	-	-	-	_
12.1	UPPER ARM w/Distance adjuster	CB2ADA	1	CB2BDA	1
12.2	LOWER ARM w/Distance adjuster	CB2ADB	1	CB2BDB	1
12.3	BUSHING for Lower Arm	CB1ADCD	1	CB1ADCD	1
12.4	REMOVABLE SLEEVE	CB2ADAS	2	CB2ADAS	2
	BRUSH DRIVE LOWER ASSEM. /UPPER ASSEM.		RB1AE		2
13.1	MOTOR MOUNT (8" lg)		B1AE		2
-	Hex head cap screw ½" -13x3"lg.	HHCS1213300			8
-	Flat washer ½" I.D.x1¼"O.D.		FW12125		
-	Split lock washer ½ " Hex nut ½ "-13		SLW12 HN1213		
13.2	HYDRAULIC MOTOR, displacement 5.0 [cu.in./rev.]		11N121. 31ADB		8 2
13.3	- Fitting 90°elbow ½" NPTM x ½ "JIC	SAE070202-8-8			4
-	- Hex head cap screw $3/8$ "- $16x^{3}/4$ " lg.	HHCS3816075			8
	SPLIT TAPER BUSHING 1"	STB-P1X100			2
	(set w/two socket set screws 1/4 "-20x 1/2 "lg., carbon steel)	SSS1420050C			4
13.5	BRUSH CONNECTING DISK	RB2AEB-P1-1-0106			2
-	Hex head cap screw ½" -13x1¼" lg.	HHCS1213125			8
-	Split lock washer ½ " Hex nut ½ "-13	SLW12 HN1213			8
-					0
	SHOCK ABSORBER ASSEMBLY:	RB1AF		2	
	SPRING SHOCK ABSORBER UHMW bushing 3/8"I.D.	RB1AFA			2
14.2	Spring adjuster assembly (aluminum 2-piece collar):	RB1AFA1 RB2AFB			4
-	- Aluminum adjuster (2-piece collar)	RB2AFB1			2
-	- Hex head cap screw 4 -20 x 14 lg.	HHCS1420125			2 4
-	- Hex nut 1/4 "-20	HN1420			4
-	Plastic Spacer	RB1AFC			2
	PIN Ø3/8"x3"lg.		TB1AEA		
	COLLAR 3/8" FRONT MOUNT:		WA1FC		4 4
14.6	FRONT MOUNT: - Clevis	RB1AG WA2GA1			2
_	- Threaded rod ½" -13x5"lg.		A2GA A2GA		2
_	- Hex nut ½"-13		IN121		2
-	- Pin 3/8"x1½"lg.		VA1GI		6
-	- Collar 3/8"		WA1FC		2 2
	- Shock mount		B1AG.		2
	REAR MOUNT w/PIN	RE	31ABA	M	2
				4.12.5.54	0.75
	LOWER BRUSH 21" / UPPER 51" ASSEMBLY:	CB1AMA			2/2
	Brush Cloth	CB1AMA-21/CB1AMA-51		2/2	
15.1		CD1 ANG	21/00	1 A M C 51	2/2
15.1 15.2 15.3	Aluminum Extrusion Two-piece Collar 1½"x12 core	CB1AMC- CB1AMB-			2/2 2/2




ITEM	Description	PART NUMBER	QTY.
16	WRAP AROUND SHAFT ASSEMBLY:	WA5K	2
16.1	Motor Mount	WA5KA	2
-	Motor Retaining Screw:	-	4
-	Hex Head Cap Screw 3/8"-16x 3/4 "lg.	HHCS3816075	4
-	Nylon Lock Nut 3/8"-16	NLN3816	4
16.2	Hydraulic Motor, displacement 11.9 [cu.in./rev.], Parker TB0195FP100AAAB	TB0195-WA1KM	2
16.3	Fitting 90° Elbow ½ "NPTM x ½ "JIC	SAE070202-8-8	4
16.4	Torque Plate	WA1K1	2
-	Hex Head Cap Screw 3/8"-16x 3/4 "lg. (motor's fastener)	HHCS3816075	8
16.5	Brush Shaft Æ1½"x10½"lg.	WA5KB	2
16.6	4-bolt Bearing 1½" UCF208-24E	WA1KCB	4
-	Screw Fastener Set (for bearing):	-	16
-	Hex Head Cap Screw ½"-13x1¾"lg.	HHCS1213175	16
-	Flat Washer ½ "I.D.x1"O.D.	FW12100	16
-	Split Lock Washer 1/2"	SLW1/2	16
-	Hex Nut ½"-13	HN1213	16
17	BRUSH ASSEMBLY (design:5" core, 72" LG)	WA1M-5/10x72	2
_	HYDRAULIC & WATER INSTALLATION:	WA1L	-
-	Side Water Manifold Assembly (on exit legs):	WA1LA	2
-	Water Manifold (tubing 1"O.D. x 36"lg., w/4 water outlets 11" apart)	WA1LAA	2
-	Hollow Hex Plug ½"NPTM	SAE140109P-8	2
-	Barb ½"x ½ "NPTM	BRB1/2x1/2	2
-	Nozzle ¼"NPTM	NZ1/4	10
-	Water Hose ½"I.D. (braid reinforced polyurethane tubin	-	
-	Pipe Clamp ³ / ₄ ", for water hose and side water manifolds (w/screw fasteners ¹ / ₄ ")	PPP3/4	10
	Hydraulic Tube Assemblies:	-	
-	Hydraulic Tubes ½ "O.D.xW.035" stainless steel TP304/TP304L ASTM A269	-	
-	Tube Support Sleeves ½ "JIC	SAE070115-8	
-	Nuts ½"J	SAE070110-8	
	Hydraulic Hose Assembly:	WA1LB	8
-	Hydraulic Hose 3/8"I.D.x34"lg., thermoplastic, "Aeroquip" FC372-06	SAE100R7-06x34	8
-	Crimp Fitting SAE 37° JIC swivel (female)	FC5810-0806	4
	"Aeroquip"	(10655-8-6)	(4)
-	(or Catching Fluidpower-"Parker")		
	Crimp Fitting SAE 37° JIC male flare	FG5005 0005	10
-	"Aeroquip"	FC5807-0806	12
	(or Catching Fluidpower-"Parker")	(10355-8-6)	(12)
	Damping Clamp 1/2", for hydraulic tubes (w/screw fasteners 1/4")	DMP1/2	8




Patent # 5898966

WRAP CONTOUR COMBO PIPE DIAGRAM



DETAIL Passenger's Side Contour Connection Detail



DETAIL Wrap Connection Detail





Figure 2

In order to get a higher application pressure at either driver side or passenger side of the machine, move the bottom bearings towards the its center, or away from the center to achieve lower application pressure.

<u>note</u>: Application pressure is the pressure of the brush applied onto the car.

Fine tuning adjustment for getting better performance of AVW Wraps

- The RPM of the wrap hydraulic motor should be set at approximately 60 RPM to allow brush to flare out fully.
- Set hydraulic relief pressure so that brush can start to stall, when contacting the front end of the widest vehicle and then increase ½ turn. The brush should never be able to stall on a front end of vehicle.
- Use a lot of soap and lubrication on the cloth.
- Do not use excessively worn cloth.
- Replace shock absorbers approximately every 6 months.
- Travel on back of car should not exceed 3/4 of back end of vehicle.
- Keep initial adjustments light as wraps will tend to loosen up as they break in and cloth absorbs more soap and water.
- Start adjusting with bearings straight up and down, usually no more than 1/4" of bearing travel will be required
- Set wraps for average conveyor speed, if conveyor speed increases or decreases more than 25 cars per hour up or down (50 cars per hour range) additional adjustment may be required.

Flex coupler fails or twists

Possible Causes & Troubleshooting:

- •Torque settings on hydraulics is set too high.
- Flex coupler should be replaced approx. every 200,000 cars.






Figure 2

Brush climb up on back ends of the car

Possible Causes & Troubleshooting:

- The car is rolling ahead because of uneven floor and stopping with wrap on rear of car.
- Torque (Pressure) is set too high and brush will not stall as it climbs.
- Brush speed may be too fast. set at 60 RPM
- Brush may be set to travel more than 3/4 of backend of car / more swing after break- in period.
- Keep pivot point low as possible try not to mount over tire brushes or where high clearance is needed off the floor.
- Car may be stopping or rolling because of a treadle on floor or pocket in floor
- If the friction is too high-apply more soap or lubrication.
- The faster the brush RPM, the more travel on the back of the vehicle-adjust RPM.

Figure 3



Mirror is damaged or broken

Possible Causes & Troubleshooting:

- Lower portion of the brush is set to high coming into contact with mirror-stay below 33" from the top of the lower fuller section of the brush.
- Arm is restricted not to swing out far enough to clear the vehicle-adjust the bumper so that brush can clear the vehicle.
- Too much tilt on the bearing causing excessive side pressure –adjust the tilt on the bearing to reduce the pressure.
- Weak shocks absorbers-replace shock absorbers.
- Brush speed incorrect-set the speed.

